

DIR-619L Firmware Release Notes

Firmware: FW115CNB01

Hardware: A1

Date: 2012/1/21

Note:

1. FW version is advanced to v1.15
2. Pre-configured SSID is changed to "D-Link_DIR-619L".

Problems Resolved:

1. Fixed the Oray DDNS bug reported by DCN.
2. Fixed the issue of dependency between SYSLOG and EMAIL Function.
3. Fixed the issue of the wizard flow.
4. Fixed the log display issue
5. Fixed the smart check issue of entering WLAN password
6. Fixed the issue of missing admin password option in mydlink setup flow.

Enhancements:

1. Improved wireless sensitivity of wireless client by enabling 2 beacon mode.
2. New Style of Wizard Setup Flow
3. Extended the character number support of email setting to 128.
4. Supported the double NAT Detection.
5. Added QRS Mobile App Support.
6. Added mydlink setting page.
7. Added the character number limitation of Admin password
(Minimum 6 characters, Maximum 15 characters)

Known Issues:

None